



Bonnie View  
Golf Course &  
Country Club  
Site

Location and position of mine shafts and underground workings are very approximate from available data. Underground workings projected from longitudinal section in 1865 Annual report of the Company, and reported depth of shaft in 1887 (Moore, 1935)

EXPLANATION	
	Inclined shaft
	Bottom of inclined shaft
	Inferred underground workings, projected in shaft
	Caved adit
	Small open pit or trench
	Prospect pit
	Mine dump
	Building
	Building site

Map of the Bare Hills Copper Mine from 1957 projection made by Heyl and Pearre.

Attachment E  
Bonnie View Golf Course &  
Country Club, Baltimore, MD  
Heyl & Pearre 1957 Map of  
Bare Hills Copper Mine  
Source: MD Geological Survey